

Tweed Laboratory Centre, 46 Enterprise Avenue, Tweed Heads South NSW 2486 Australia
Phone: 07 5569 3103 Fax: 07 5524 2676 Email: samplerception@tweed.nsw.gov.au ABN: 90 178 732 496
(All correspondence: Tweed Shire Council PO Box 816 Murwillumbah NSW 2484)
www.tweed.nsw.gov.au/tweedlab/

FINAL CERTIFICATE OF ANALYSIS

Client: Broken Head Quarry
Address: PO Box 165
BYRON BAY
NSW 2481

Page 1 of 2

Attention: Leonie Rowe
Copy To:

Lims1 Report No: 182666
Client Job Reference: PO 08631
Date of Report: 07/08/2018

All pages of this Report have been checked and approved.
This document may not be reproduced except in full.

Taken By:	Client	No of Samples:	4
Date Taken:	01/08/2018	Date Testing Commenced:	01/08/2018
Date Received:	01/08/2018	Date Testing Completed:	06/08/2018


Sample Description: Quarry - Air Monitoring PO 08631

Sample/Site No	Sample/Site Description
SPD1	1
SPD2	2
SPD3	3
SPD4	4

COMMENTS:

Results refer to samples as received at the Laboratory.

* NATA accreditation does not cover the performance of this service.


Dr Paul J Wright
(Laboratory Coordinator)
paulw@tweed.nsw.gov.au

Tweed Laboratory Centre

Client: Broken Head Quarry

Lims1 Report No: 182666

Address: PO Box 165
BYRON BAY
NSW 2481

Date Testing Completed: 06/08/2018

Date of Report: 07/08/2018

Attention: Leonie Rowe

Sample Description: Quarry - Air Monitoring PO 08631

Sample Identification:			SPD1	SPD2	SPD3	SPD4
Date Taken:			01/08/2018	01/08/2018	01/08/2018	01/08/2018
Test	Method	Units	182666-1	182666-2	182666-3	182666-4
*Air Monitoring	P13	g/m2/mth	0.4	0.6	0.4	0.4
*Ash Content	P13	g/m2/mth	0.3	0.4	0.2	0.1

