

Tweed Laboratory Centre, 46 Enterprise Avenue, Tweed Heads South NSW 2486 Australia
Phone: 07 5569 3103 Fax: 07 5524 2676 Email: samplerception@tweed.nsw.gov.au ABN: 90 178 732 496
(All correspondence: Tweed Shire Council PO Box 816 Murwillumbah NSW 2484)
www.tweed.nsw.gov.au/tweedlab/

FINAL CERTIFICATE OF ANALYSIS

Client: Broken Head Quarry
Address: PO Box 165
BYRON BAY
NSW 2481

Page 1 of 2

Attention: Leonie Rowe
Copy To:

Lims1 Report No: 163060
Client Reference:
Date of Report: 24/08/2016

All pages of this Report have been checked and approved.
This document may not be reproduced except in full.

Taken By:	Client	No of Samples:	1
Date Taken:	17/08/2016	Date Testing Commenced:	17/08/2016
Date Received:	17/08/2016	Date Testing Completed:	24/08/2016

CHEMICAL ANALYSIS **Job Description:** BHQ Water Sample - #08186

LIMS No.	Sample/Site Identification	Sample/Site Description
163060-1	1	Water Sample


COMMENTS:

Results refer to samples as received at the Laboratory.



Accredited for compliance with ISO/IEC 17025 - testing

Accreditation No: 12754 & 13538



Darryl Capner
(Senior Technical Officer – Chemistry)
dcapner@tweed.nsw.gov.au

Tweed Laboratory Centre

Client: Broken Head Quarry

Address: PO Box 165

BYRON BAY
NSW 2481

Attention: Leonie Rowe

Lims1 Report No: 163060
Date Testing Completed: 24/08/2016
Date of Report: 24/08/2016

CHEMICAL ANALYSIS **Job Description:** BHQ Water Sample - #08186

Sample Identification: Date Taken: Test	Method	Units	Water Sample 17/08/2016 163060-1
pH	P1	pH units	5.2
Suspended Solids	P4	mg/L	98
Turbidity	P8	NTU	182

