

Tweed Laboratory Centre, 46 Enterprise Avenue, Tweed Heads South NSW 2486 Australia
Phone: 07 5569 3103 Fax: 07 5524 2676 Email: samplerception@tweed.nsw.gov.au ABN: 90 178 732 496
(All correspondence: Tweed Shire Council PO Box 816 Murwillumbah NSW 2484)
www.tweed.nsw.gov.au/tweedlab/

FINAL CERTIFICATE OF ANALYSIS

Client: Broken Head Quarry Page 1 of 2
Address: PO Box 165
BYRON BAY
NSW 2481

Attention: Leonie Rowe **Lims1 Report No:** 183762
Copy To: **Client Reference:**
Date of Report: 23/11/2018

All pages of this report have been checked and approved. This document may not be reproduced except in full.

Taken By: Client **No of Samples:** 4
Date Taken: 07/11/2018 **Date Testing Commenced:** 07/11/2018
Date Received: 07/11/2018 **Date Testing Completed:** 19/11/2018

CHEMICAL REPORT Job Description: Quarry - Air Monitoring PO8637

LIMS No.	Sample/Site Identification	Sample/Site Description
183762-1	SPD1	1
183762-2	SPD2	2
183762-3	SPD3	3
183762-4	SPD4	4


Dr Paul J Wright
(Laboratory Coordinator)
paulw@tweed.nsw.gov.au

Client: Broken Head Quarry

Address: PO Box 165

 BYRON BAY
 NSW 2481

Attention: Leonie Rowe

Lims1 Report No: 183762

Date Testing Completed: 19/11/2018

Date of Report: 23/11/2018

CHEMICAL REPORT Job Description: Quarry - Air Monitoring PO8637

REPORT COMMENTS

Additional information relevant to this report can be found in the Sample Receipt Notice and Chain of Custody. Measurement Uncertainty available upon request.

Key: LOR = Limit of reporting
 ^ = NATA accreditation does not cover the performance of this service
 * = Value is considered an estimate
 NP = Not present
 < = Less than
 > = Greater than

ANALYSIS RESULTS

Sample Identification:			SPD1	SPD2	SPD3	SPD4
Date Taken:			07/11/2018	07/11/2018	07/11/2018	07/11/2018
Test	Method	Units	183762-1	183762-2	183762-3	183762-4
^Air Monitoring	P13	g/m2/mth	<0.1	0.3	0.1	0.1
^Ash Content	P13	g/m2/mth	<0.1	0.1	0.1	0.1

