

Tweed Laboratory Centre, 46 Enterprise Avenue, Tweed Heads South NSW 2486 Australia
Phone: 07 5569 3103 Fax: 07 5524 2676 Email: samplerception@tweed.nsw.gov.au ABN: 90 178 732 496
(All correspondence: Tweed Shire Council PO Box 816 Murwillumbah NSW 2484)
www.tweed.nsw.gov.au/tweedlab/

FINAL CERTIFICATE OF ANALYSIS

Client: Broken Head Quarry
Address: PO Box 165
BYRON BAY
NSW 2481

Page 1 of 2

Attention: Leonie Rowe
Copy To:

Lims1 Report No: 172693
Client Job Reference: PO8200
Date of Report: 15/08/2017

All pages of this Report have been checked and approved.
This document may not be reproduced except in full.

Taken By:	Client	No of Samples:	4
Date Taken:	02/08/2017	Date Testing Commenced:	02/08/2017
Date Received:	02/08/2017	Date Testing Completed:	15/08/2017


Sample Description: Quarry - Air Monitoring PO8200

Sample/Site No	Sample/Site Description
1	SPD1
2	SPD2
3	SPD3
4	SPD4

COMMENTS:

Results refer to samples as received at the Laboratory.

* NATA accreditation does not cover the performance of this service.


Dr Paul J Wright
(Laboratory Coordinator)
paulw@tweed.nsw.gov.au

Tweed Laboratory Centre

Client: Broken Head Quarry

Lims1 Report No: 172693
Date Testing Completed: 15/08/2017
Date of Report: 15/08/2017

Address: PO Box 165
 BYRON BAY
 NSW 2481

Attention: Leonie Rowe

Sample Description: Quarry - Air Monitoring PO8200

Sample Identification:			1	2	3	4
Date Taken:			02/08/2017	02/08/2017	02/08/2017	02/08/2017
Test	Method	Units	172693-1	172693-2	172693-3	172693-4
*Air Monitoring	P13	g/m2/mth	0.1	<0.1	0.3	0.2
*Ash Content	P13	g/m2/mth	0.1	<0.1	0.2	0.1

