



Tweed Laboratory Centre, 46 Enterprise Avenue, Tweed Heads South NSW 2486 Australia
 Phone: 07 5569 3103 Fax: 07 5524 2676 Email: samplerception@tweed.nsw.gov.au ABN: 90 178 732 496
 (All correspondence: Tweed Shire Council PO Box 816 Murwillumbah NSW 2484)
www.tweed.nsw.gov.au/tweedlab/

FINAL CERTIFICATE OF ANALYSIS

Client: Broken Head Quarry
Address: PO Box 165
 BYRON BAY
 NSW 2481

Page 1 of 2

After a significant rain event, 330mm. in 10 days.

Attention:	Dave Morris	Lims1 Report No:	14/2271-C
Copy To:	Sheree Essery - BSC	Client Reference:	8010Q
		Date of Report:	10/09/2014

All pages of this Report have been checked and approved.
 This document may not be reproduced except in full.

Taken By:	Client	No of Samples:	2
Date Taken:	28/08/2014	Date Testing Commenced:	28/08/2014
Date Received:	28/08/2014	Date Testing Completed:	09/09/2014

Sample Description: Quarry Water Samples - Chemical

Sample/Site No	Sample/Site Description
1	EPA 1
2	EPA 2

COMMENTS:

Results refer to samples as received at the Laboratory.



Accredited for compliance with ISO/IEC 17025

Accreditation No: 12754 & 13538

Paul J Wright
 Dr Paul J Wright
 (Laboratory Coordinator)
paulw@tweed.nsw.gov.au

Tweed Laboratory Centre

Client: Broken Head Quarry

Address: PO Box 165

BYRON BAY
NSW 2481

Attention: Dave Morris

Lims1 Report No: 14/2271-C
Date Testing Completed: 09/09/2014
Date of Report: 10/09/2014

Sample Description: Quarry Water Samples - Chemical

Sample Identification:			EPA 1	EPA 2
Date Taken:			28/08/2014	28/08/2014
Date Received:			28/08/2014	28/08/2014
Date Testing Commenced:			28/08/2014	28/08/2014
Test	Method	Units	14/2271-C-1	14/2271-C-2
Oil and Grease	C8	mg/L	<2	--
Suspended Solids	P4	mg/L	194	52

