

Laboratory Report

Customer: Broken Head Quarry
Attention: D. Hart
Address: PO Box 165, Byron Bay, NSW 2481

Sample Information: Process Dam
Date Sampled: 29-10-08
Date Received: 29-10-08
Order No: 05761Q
Report No: BHQ_10966
Report Date: 30th October 2008

Sample/Site		Process Dam
BEL. No.	083377	
Testing Date	29-10-08	
pH (pH units)		4.5

This document shall not be reproduced except in full.
 Results refer to samples as received at the laboratory




 Shirley Atkinson
 Laboratory Manager



This document is issued in accordance with
 NATA's accreditation requirements.
 Accredited for compliance with ISO/IEC 17025
 Number 14435