

Tweed Laboratory Centre, 46 Enterprise Avenue, Tweed Heads South NSW 2486 Australia  
Phone: 07 5569 3103 Fax: 07 5524 2676 Email: [samplerception@tweed.nsw.gov.au](mailto:samplerception@tweed.nsw.gov.au) ABN: 90 178 732 496  
(All correspondence: Tweed Shire Council PO Box 816 Murwillumbah NSW 2484)  
[www.tweed.nsw.gov.au/tweedlab/](http://www.tweed.nsw.gov.au/tweedlab/)

## FINAL CERTIFICATE OF ANALYSIS

**Client:** Broken Head Quarry  
**Address:** PO Box 165  
BYRON BAY  
NSW 2481

Page 1 of 2

**Attention:** Leonie Rowe  
**Copy To:**

**Lims1 Report No:** 183063  
**Client Job Reference:** PO:08634  
**Date of Report:** 28/09/2018

All pages of this Report have been checked and approved.  
This document may not be reproduced except in full.

**Taken By:** Laboratory Staff  
**Date Taken:** 05/09/2018  
**Date Received:** 05/09/2018

**No of Samples:** 4  
**Date Testing Commenced:** 05/09/2018  
**Date Testing Completed:** 28/09/2018

**Sample Description:** Quarry - Air Monitoring PO:08634

Sample/Site No	Sample/Site Description
SPD1	1
SPD2	2
SPD3	3
SPD4	4

### COMMENTS:

Results refer to samples as received at the Laboratory.

\* NATA accreditation does not cover the performance of this service.

  
Darryl Capner  
(Principal Scientific Officer)  
[dcapner@tweed.nsw.gov.au](mailto:dcapner@tweed.nsw.gov.au)

## Tweed Laboratory Centre

**Client:** Broken Head Quarry

**Lims1 Report No:** 183063

**Address:** PO Box 165  
BYRON BAY  
NSW 2481

**Date Testing Completed:** 28/09/2018

**Date of Report:** 28/09/2018

**Attention:** Leonie Rowe

**Sample Description:** Quarry - Air Monitoring PO:08634

Sample Identification:			SPD1	SPD2	SPD3	SPD4
Date Taken:			05/09/2018	05/09/2018	05/09/2018	05/09/2018
Test	Method	Units	183063-1	183063-2	183063-3	183063-4
*Air Monitoring	P13	g/m2/mth	0.4	0.8	0.5	0.9
*Ash Content	P13	g/m2/mth	0.2	0.5	0.3	0.3

