

Tweed Laboratory Centre, 46 Enterprise Avenue, Tweed Heads South NSW 2486 Australia
Phone: 07 5569 3103 Fax: 07 5524 2676 Email: samlereception@tweed.nsw.gov.au ABN: 90 178 732 496
(All correspondence: Tweed Shire Council PO Box 816 Murwillumbah NSW 2484)
www.tweedlab.com.au

FINAL CERTIFICATE OF ANALYSIS

Client: Broken Head Quarry Page 1 of 2
Address: PO Box 165
BYRON BAY
NSW 2481

Attention: Dave Morris **Lims1 Report No:** 12/1528-C
Copy To: Sheree Essery - BSC **Client Job Reference:** O/N: 05208Q
Date of Report: 20/06/2012

All pages of this Report have been checked and approved.
This document may not be reproduced except in full.

Taken By: Client **No of Samples:** 4
Date Taken: 06/06/2012 **Date Testing Commenced:** 06/06/2012
Date Received: 06/06/2012 **Date Testing Completed:** 20/06/2012

Sample Description: Broken Head Quarry Air Monitoring - Chemical

Sample/Site No	Sample/Site Description
1	SPD1
2	SPD2
3	SPD3
4	SPD4

COMMENTS:

Results refer to samples as received at the Laboratory.

* Tests not covered by NATA accreditation.

No sample received for SPD4 (container broken).


Dr Paul J Wright
(Laboratory Coordinator)
paulw@tweed.nsw.gov.au

Tweed Laboratory Centre

Client: Broken Head Quarry

Lims1 Report No: 12/1528-C

Address: PO Box 165
BYRON BAY
NSW 2481

Date Testing Completed: 20/06/2012

Date of Report: 20/06/2012

Attention: Dave Morris

Sample Description: Broken Head Quarry Air Monitoring - Chemical

Sample Identification:			1	2	3	4
Date Taken:			06/06/2012	06/06/2012	06/06/2012	06/06/2012
Date Received:			06/06/2012	06/06/2012	06/06/2012	06/06/2012
Date Testing Commenced:			06/06/2012	06/06/2012	06/06/2012	06/06/2012
Test	Method	Units	12/1528-C-1	12/1528-C-2	12/1528-C-3	12/1528-C-4
*Air Monitoring	--	g/m2/mth	1.5	1.1	0.8	--
*Ash Content	--	g/m2/mth	0.2	<0.1	0.3	--

