

Tweed Laboratory Centre, 46 Enterprise Avenue, Tweed Heads South NSW 2486 Australia
Phone: 07 5569 3103 Fax: 07 5524 2676 Email: samplerception@tweed.nsw.gov.au ABN: 90 178 732 496
(All correspondence: Tweed Shire Council PO Box 816 Murwillumbah NSW 2484)
www.tweed.nsw.gov.au/tweedlab/

FINAL CERTIFICATE OF ANALYSIS

Client: Broken Head Quarry
Address: PO Box 165
BYRON BAY
NSW 2481

Page 1 of 2

Attention: Dave Morris
Copy To: Sheree Essery - BSC

Lims1 Report No: 13/3346-C
Client Job Reference: O/N: 05678Q
Date of Report: 18/12/2013

All pages of this Report have been checked and approved.
This document may not be reproduced except in full.

Taken By:	Client	No of Samples:	4
Date Taken:	04/12/2013	Date Testing Commenced:	04/12/2013
Date Received:	04/12/2013	Date Testing Completed:	18/12/2013


Sample Description: Broken Head Quarry Air Monitoring - Chemical

Sample/Site No	Sample/Site Description
1	SPD1
2	SPD2
3	SPD3
4	SPD4

COMMENTS:

Results refer to samples as received at the Laboratory.

* Tests not covered by NATA accreditation.



Tania Collins
(Instrument Analyst)
tcollins@tweed.nsw.gov.au

Tweed Laboratory Centre

Client: Broken Head Quarry

Lims1 Report No: 13/3346-C

Address: PO Box 165
BYRON BAY
NSW 2481

Date Testing Completed: 18/12/2013

Date of Report: 18/12/2013

Attention: Dave Morris

Sample Description: Broken Head Quarry Air Monitoring - Chemical

Sample Identification:			1	2	3	4
Date Taken:			04/12/2013	04/12/2013	04/12/2013	04/12/2013
Date Received:			04/12/2013	04/12/2013	04/12/2013	04/12/2013
Date Testing Commenced:			04/12/2013	04/12/2013	04/12/2013	04/12/2013
Test	Method	Units	13/3346-C-1	13/3346-C-2	13/3346-C-3	13/3346-C-4
*Air Monitoring	--	g/m2/mth	1.8	1.6	1.7	10
*Ash Content	--	g/m2/mth	1.2	0.5	1	9.0

